



Schweissnähte

585 x 8 = 3510

200 x 8 = 1600

50 x 8 = 400

17 x 8 = 136

23 x 8 = 184

160 x 1 = 160

Schweissnähte ges. 5990 mm

Vorderansicht  
Maßstab: 1:5